

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**



Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**






FIG. 3




FIG. 2








FIG. 4







NOTE:  
REINFS & SIDE INNER  
ARE MOLDED TOGETHER

FLOOR ASSEMBLY  
321

Fig. 8

REINFORCEMENT  
319A

FIXING

SIDE  
OUTER  
311

INNER  
MOLDING  
319B


FOAM  
339

FIXING

VERTICAL SECTION

REINFORCEMENT BACK ASSEMBLY

FIG. 10A



WINDOW  
OPENING

SIDE INNER  
MOLDING

REINFORCEMENT

FIXING

FIG. 10B

SIDE  
OUTER

FOAM

TRANSITION  
INNER

TRANSITION  
OUTER

FRONT  
SECTION

FIG. 9

